

TN Buchanan
S.W.D.

Green Bay

February 18, 1971

Division of Environmental Protection

TO: Thomas G. Frangos
ATTN: Glen Bishop
FROM: James L. Lissack
SUBJECT: Lehrer Sanitary Landfill Operation, Outagamie County,
Town of Buchanan

This writer conducted a field investigation on February 18, 1971, of Lehrer Brothers Sanitary Landfill. The following were noted:

1. Compacting and covering was being conducted.
2. Wood and bark chips were being utilized to create a stable working surface and to sponge up water from thawing snow. This appeared to be working excellently.
3. An attendant was on duty.
4. A large container was placed at the entrance of the site for dumping of garbage from local town residents. This container, when full, is dumped into the landfill. This container is to curtail small traffic from the site.
5. Mr. Lehrer was contacted and indicated no burning is done. No evidence of burning was found.
6. The dumping area to the south of the landfill has been discontinued. All refuse is now being placed in the sanitary landfill portion.

It is the conclusion of this writer that the sanitary landfill operated by Lehrer Brothers is being conducted in conformance with Chapter RD 51.

By _____
Dennis C. Weisensel
Environmental Technician

DCW:jp

NOTED:

00554

Date

DEPARTMENT OF NATURAL RESOURCES
Solid Waste Disposal - Site Evaluation

Licensee Lehrer Brothers License No. _____

Officials: (Mayor, Chairman, Pres.) _____

(Clerk) _____

Responsible Person _____ Phone _____

Location Outagamie Buchanan
(county) (township) ($\frac{1}{4}$ sec., town, range)

Type of Operation S.L.F. Population served _____

Distances to: surface water _____ nearest dwelling 1/2 mile

groundwater _____ bedrock _____ S.T.H. 1/2 mile 55"

OPERATION CHECK LIST	YES	NO	REMARKS
Screened from view	(<input checked="" type="checkbox"/>)	()	
Lockable gate at entrance	(<input checked="" type="checkbox"/>)	()	
Regulatory signs posted	()	(<input checked="" type="checkbox"/>)	entrance by permit only
All-weather approach road	(<input checked="" type="checkbox"/>)	()	
Nuisance free (odors, loose paper, etc.)	(<input checked="" type="checkbox"/>)	()	
Site fenced	()	(<input checked="" type="checkbox"/>)	Last several pieces of equipment in fire.
Operator on duty	(<input checked="" type="checkbox"/>)	()	
Compaction and covering	(<input checked="" type="checkbox"/>)	()	old portion closed to public and not being used.
Equipment available	(<input checked="" type="checkbox"/>)	()	
Putrescible material covered	(<input checked="" type="checkbox"/>)	()	
Rodent and insect control	()	()	
Burning practiced	()	(<input checked="" type="checkbox"/>)	
Fire hazard in area	()	(<input checked="" type="checkbox"/>)	
Hazardous material at site	()	(<input checked="" type="checkbox"/>)	
Site subject to flooding	()	(<input checked="" type="checkbox"/>)	
Local official contacted	(<input checked="" type="checkbox"/>)	()	
Permit required (60.72 Stats.)	(<input checked="" type="checkbox"/>)	()	
Comments			<u>See</u>
Date visited	<u>2.18.71</u>		Evaluation by <u>D.W.</u>

00553